


Anschluß Pneumatikbox – Steuerung / connection pneumatic box – control box (LipuSmart-P-OB / -OD)


Drucksensor Hebeanlage /
Pressure sensor lifting plant

1



2

Menüpunkte (obere Zeile)	Menu items (top line)	Einstellungen (untere Zeile)	Settings (bottom line)
Niveau-Steuerung	Level control	4 – 20 mA Interface	2 b
20mA => Pegel	Range Pres Sensor	250 cm	



Lufteinperlung /
Air bubble injection

